

## DMAC Additional Safety Rules

---

- 1) New Planes, Gliders and Heli's to be checked by at least 3 committee members or a combination of committee member and experienced modellers before First flight.
- 2) New Planes Gliders and Heli's needing to be test flown. The Pilot at the controls will be Bronze wing minimum at controls when there is more than one member present at the club.  
  
2a) If you want to test fly your own Plane and you do not have Bronze Wings, you can Test fly on Monday To Saturday any time, Sunday 8am till 9am as long as no other member or visiting members are not present at time of test flight, refer to rule 2.
- 3) New Pilots to have a mentor or Buddy connection for as long as required (IE) Bronze wings achieved.
- 4) Gliders to be launch by another member other than Pilot on club days or if more than one member flying on the day.
- 5) All members flying will range check at start of flying session.
- 6) Electric Aircraft will have Batteries connected at flight line.
- 7) If you would like Solo air time to Fly talk to the guy's on the Day if ok arrange a time to take off.
- 8) You will ask every pilot at the Flight line if ok to take off before doing so no exceptions.
- 9) IC Planes to be carried to Flight line by another member not the pilot when there is more than one member at club.
- 10) All these are mandatory when more than one member or visiting member are using or present at the field.